

Extractor Warranty Items, Replacement Parts List, And Disclaimers

Part	Description	Expected Service	5-year replacement quantity per sled	Warranty Item	\$\$ each	Qty.
1	Sled Hand Grip	3-5 years	4	yes (30 days)	\$14.00	
2	Hand Grip plug & Screw (Handcraft sled)	3-5 years	2	yes (1 year)	\$2.00	
	EXTRACTOR PRO Hull with deck pad	3-5 years	1	yes (30 days)	\$650.00	
	EXTRACTOR PRO Drain Plug & Hex Key	3-5 years	2	no	\$5.00	
3	Velcro Quick Hitch Boot	2-3 years	2	yes (30 days)	\$100.00	
4	Aluminum Sled Nose Plate	3-5 years	1	yes (Lifetime on welds)	\$150.00	
5	Aluminum Clevis Pin Quick Hitch	3-5 years	2 (personnel tend to lose or misplace these)	yes (1 year)	\$40.00	
	Aluminum Clevis Pin Tie Down	3-5 years	1 (personnel tend to lose or misplace these)	yes (1 year)	\$20.00	
6	Clevis Lynch Pin	3-6 months	10 (personnel tend to lose these items)	no	\$1.00	
7	Stainless braided Lanyard	6 months to 1 yr	5 (personnel tend to lose these items)	no	\$6.00	
8	Nose Plate Allen Screws & Washers	5 + years	zero	no	\$0.50	
9	Stainless Triangular Hitch Bar	3 months to 5+ yrs	1-3 (Depends on usage amount or accidents)	yes (Lifetime on welds)	\$175.00	
	Tie Down Center Pad Eye Tube	1-3 years	1	yes (Lifetime on welds)	\$50.00	
10	Urethane match plates	1-3 years	2	yes (30 days)	\$30.00	
11	Urethane tow pad	1-3 years	2	yes (30 days)	\$50.00	
	Tie Down Bumper Pieces (Set of 2)	1-3 years	2	yes (30 days)	\$35.00	
12	Stainless bottom Matching plate	1-5 years	1	yes (1 year)	\$30.00	
13	Stainless Elevated Hitch Receiver Box	1-5 years	1 (depends on if pwc model is changed or not)	yes (Lifetime on welds)	\$250.00	
14	Stainless Hex Bolt 3/4 "-10 x 2.5" long	5 + years	zero	no	\$3.50	
15	Stainless Hex Bolt 3/4 "-10 x 3.0" long	5 + years	zero	no	\$4.00	
16	Stainless Hex Bolt 3/4 "-10 x 3.5" long	5 + years	zero	no	\$4.50	
17	Stainless Hex Bolt 3/4 "-10 x 4.0" long	5 + years	zero	no	\$5.00	
18	Stainless Hex Bolt 3/4 "-10 x 4.5" long	5 + years	zero	no	\$5.50	
19	Stainless Hex Bolt 3/4 "-10 x 5.0" long	5 + years	zero	no	\$6.00	
20	Stainless 3/4"x 1.75" dia. flat washer	5 + years	zero	no	\$2.00	
21	Stainless 3/4" Lock washer	5 + years	zero	no	\$2.00	
22	Stainless 3/4" -10 Nut	5 + years	zero	no	\$2.00	
23	Stainless 3/4" -10 Slim Jamb Nut	5 + years	zero	no	\$3.50	

DISCLAIMERS:

Extractor reserves the right to make specification modifications or design changes to the existing product line. In the event that Extractor makes these design changes, Extrac

These replacement parts shall be of original design or of modified, improved design from the original part.

The above replacement parts list is only a guideline and does not represent an expected list of parts that will need to be replaced over a 5-year period. Under normal operations as recommended by Extractor and in practicing the recommended Maintenance Guidelines, the above list represents the maximum number of parts that would need to be replaced over a 5 -year period. Many customers who follow the guidelines have not required these spare parts.

Extractor is the sole source manufacturer of the pwc rescue sled with solid hitch attachment under U.S. Utility Patent 5, 354,222 and other patents pending.

All materials, craftsmanship, and design specifications have been tested for safe use according to the recommended guidelines as stated by Extractor.

Although this device is currently used and recognized by many lifesaving agencies internationally, it has not gone through certification testing by an independent laboratory, nor have any national or international standards or requirements been established for a pwc sled device to date. Extractor makes its claims based on its products use professionally within the working environment since 1991. Extractor warrants the pwc sled product and individual parts for the specified period(s) and for safe and successful use as long as the recommended guidelines are adhered to, and so long as the personnel are properly trained for its use. Extractor does not guarantee this device to save lives and will not be responsible for accidental injury, drowning, death, or damage to sled or pwc as a result of failure to adhere to recommended guidelines, use by improperly trained personnel, or by act of nature beyond human control.